

215040887
62894

State of Nebraska
Investigator's Motor Vehicle Accident Report

Sheet 1 of 2

2	Total Number of Vehicles	Local No./ District 62	Agency Case No. B5-093032	HIT & RUN? <input type="radio"/> YES <input checked="" type="radio"/> NO	INVESTIGATION MADE AT SCENE? <input checked="" type="radio"/> YES <input type="radio"/> NO	L 1
A/1 01	DATE OF ACCIDENT	M M / D D / Y Y Y Y S M T W T H F S 10/06/2015		TIME OF ACCIDENT 1102	STATE USE ONLY	
A/2	PLACE OF ACCIDENT	COUNTY Lancaster	CITY Lincoln	POLICE NOTIFIED 1102	10/06/2015	
B 66	ROAD ON WHICH ACCIDENT OCCURRED	STREET/ HIGHWAY NO. 33rd/L		PRIVATE PROPERTY? <input type="radio"/> YES <input checked="" type="radio"/> NO	LATITUDE	
C 1	DISTANCE FROM MILEPOST	FEET	N S E W OF MILEPOST	HIGHWAY NO.	LONGITUDE	
D 1	IF AT INTERSECTION		IF NOT AT INTERSECTION			
NAME OF INTERSECTING ROADWAY		O FEET O MILES N S E W		OF NEAREST STREET, BRIDGE, RAILROAD CROSSING		
L						
V1/M 01	IF ACCIDENT WAS OUTSIDE CITY LIMITS, INDICATE DISTANCE FROM NEAREST TOWN					
V2/M 20	MILES	N S E W	AND MILES	N S E W	OF NEAREST CITY OR TOWN	
E 2	R. WORK ZONE CODES	R1 R2 R3 R4	S. PEDESTRIAN CLASSIFICATION CODES	S1 S2 S3 S4 S5-a S5-b S6-a S6-b	DOES ACCIDENT INVOLVE DAMAGE TO STATE DEPT. OF ROADS' PROPERTY? <input type="radio"/> YES <input checked="" type="radio"/> NO	
VEHICLE NO. 1						
F 1	DRIVER LICENSE NO.	H13307182		STATE (Of License)	NE	SEX <input type="radio"/> FEMALE <input checked="" type="radio"/> MALE
V1/N 1	DRIVER	DANIEL L SOUTH		PHONE	308-380-7857	
V2/N 1	DRIVER ADDRESS	CITY, STATE, ZIP		DATE OF BIRTH (MM / DD / YYYY)	07/29/1992	
G 2	OWNER	DAVID A SOUTH / Daniel L South		PHONE	308-379-4485	
V1/O 3	VEHICLE	2007	Dodge	Charger	4 door Sedan	white
V2/O 1	VEHICLE ID NO. (VIN)	2B3KA43G27H809044		INSURANCE COMPANY	Farm Bureau	
I 1	VEHICLE	2007	Dodge	Charger	4 door Sedan	white
V1/P 1	VEHICLE	2007	Dodge	Charger	4 door Sedan	white
V2/P 8	VEHICLE	2007	Dodge	Charger	4 door Sedan	white
J 01	VEHICLE	2007	Dodge	Charger	4 door Sedan	white
V1/Q 1	VEHICLE	2007	Dodge	Charger	4 door Sedan	white
V2/Q 4	VEHICLE	2007	Dodge	Charger	4 door Sedan	white
K 03	VEHICLE	2007	Dodge	Charger	4 door Sedan	white
Complete this section for all injured persons (Complete a continuation report, if more than three were injured)						
VEH. #	NAME	ADDRESS		DATE OF BIRTH (MM / DD / YYYY)	1 Seat Position	2 Eject
VEH. #	NAME	ADDRESS		DATE OF BIRTH (MM / DD / YYYY)	3 Body Region	4 Injury Sev.
VEH. #	NAME	ADDRESS		DATE OF BIRTH (MM / DD / YYYY)	5 Trans.	SEX M F
VEH. #	NAME	ADDRESS		DATE OF BIRTH (MM / DD / YYYY)	6 EMS SERVICE NAME	7 EMS RUN REPORT NO.
VEH. #	NAME	ADDRESS		DATE OF BIRTH (MM / DD / YYYY)	8 EMS SERVICE NAME	9 EMS RUN REPORT NO.
VEH. #	NAME	ADDRESS		DATE OF BIRTH (MM / DD / YYYY)	10 EMS SERVICE NAME	11 EMS RUN REPORT NO.

THE FOLLOWING INFORMATION IS REQUIRED FOR ALL ACCIDENTS

INDICATE BY DIAGRAM WHAT HAPPENED

AGENCY CASE NO.
B5-093032




Indicate
North
by Arrow

POI #1: (V#1-Pavement)
6'5" N S curb L St
8'3" E W curb 33rd

POI #2: (Wheel-V#2) Estimate
480' N N curb J St
75' W W curb 33rd St

Parking Lot
Woods Tennis Center



DESCRIPTION OF ACCIDENT BASED ON OFFICER'S INVESTIGATION

V#1 was SB on 33rd at approx. L St when the LR wheel became disengaged from the vehicle and rolled right off the roadway approx. 170' before colliding into the side of V#2, which was parked in the east lot of Woods Park. V#1 continued SB for another 117', gouging the pavement before coming to a stop. D#1 reported that he'd just had his oil changed and tires rotated at Jiffy Lube, 33rd/O and had just driven away from the business. A technician there had neglected to tighten the lug nuts, three of which were located within a block of the accident scene.

PROPERTY	OBJECT DAMAGED	OWNER NAME	ADDRESS	PHONE	APPROX. COST OF DAMAGE \$
	OBJECT DAMAGED	OWNER NAME	ADDRESS	PHONE	APPROX. COST OF DAMAGE \$
WITNESSES	NAME				PHONE
	NAME				PHONE

VEHICLE MOVEMENT BEFORE COLLISION				POINT OF IMPACT AND MOST DAMAGED AREA				AIRBAG DEPLOYED VEHICLE 1				RESTRAINT USE VEHICLE 1				TOTAL OCCUPANTS								
VEH NO.	N	S	E	W	ROAD OR HIGHWAY NAME				(Enter numbers for each vehicle)															
1		X			33rd								-								VEH 1 1 VEH 2 0			
2				X	private proper								4				2				ALCOHOL TESTING Driver No. 1 Y Driver No. 2 Y Pedestrian Y ALCOHOL LEVEL TESTED N X N X N BAC LEVEL ALCOHOL/DRUGS SUSPECTED Driver No. 1 1 Driver No. 2 5			
1	01	06 Turning left			POINT OF IMPACT 06				POINT OF IMPACT 04				1 Deployed - front				1 None used - vehicle occupant							
2	10	08 Entering traffic lane			MOST DAMAGED AREA 06				MOST DAMAGED AREA 04				2 Deployed - side				2 Lap & shoulder belt used							
01 Essentially straight ahead 02 Backing 03 Changing lanes 04 Overtaking/Passing 05 Turning right 06 Turning left 07 Making U-turn 08 Entering traffic lane 09 Leaving traffic lane 10 Parked 11 Slowing or stopped in traffic 12 Other 13 Unknown					00 None				01				3 Deployed - both front/side				3 Shoulder belt only used							
					09 Top & windows				02				4 Not deployed				4 Lap belt only used				4 Child safety seat used			
					10 Undercarriage				03				5 Not applicable/No airbag available				5 DOT approved helmet used				5 Costume helmet used			
					11 Total (all areas)				04				6 Unknown				6 Restraint use unknown				6 Restraint use unknown			
					12 Other				05				VEHICLE 2				VEHICLE 2							

OFFICER NO. 643	TROOP/TEAM/BEAT SE	DEPARTMENT Lincoln Police Department	Photographs taken? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
INVESTIGATOR NAME (Print or Type) Mark Fluitt		INVESTIGATOR SIGNATURE Approved by Mark Fluitt	DATE OF REPORT 10/06/2015